downgrading Approved For Release 2003/12/TOPCSE-RRF74B00496R000300050033-5

25X1

25X1

25X1

25X1

25X1

25X1

25X1

declassification

•	TOP SFCRFT Approved For Release 2003/12/11 : CIA-RDP74B00496R060300050033-5	25X1
		25X1
25X1	4. Maintenance: Recurrence of "O" Bay pressurization problem of new steeves at "Q" Bay connecting duct was accomplished. No malfunctions occurred in the defensive systems on this mission. There were two minor wiring problems in the collection systems but these did not prevent analysis of corrected data. Both problems have been corrected.	
	5. Communications: All communications and operated satisfactorily.	25X1
	6. Intelligence:	0EV4
	a. <u>Target Coverage</u> : There was no high resolution camera carried on this mission.	25X1
į		
:		
	7. Actions Required: None.	
	Lt.Colonel, USAF Chief, IDEALIST Division,	OSA
	Attachments - 1 Route Overlay Approved For Release 2003/1 <b>20P</b> : SEARSF74B00496R000300050033-5	25X1

25X1

**Next 1 Page(s) In Document Exempt**